

Gauge Options

Valve Accessories & Controls

Gauges are certainly not required, but often present a more professional look and provide valuable feedback for the customer. They aid in calibration and very much in troubleshooting.

A "complete gauge set" would consist of three (3) 0-160 PSI gauges (back mounted) and one(1) 0-30 PSI gauge (bottom mounted). The 0-160 gauges are for your supply port and two actuator connections-marked S, C+ & C-. This would of course, be for a double acting actuator, or possibly if you are using "air assist"* with a single acting actuator. The gauge port on the top of the positioner is for use with the V100E and is the I/P output gauge, which is furnished, as a 0-30 PSI-this gauge is bottom mounted for better visibility by the customer. Gauges are 1/8" NPT, 1 ½" size-aluminum or stainless.

Therefore your gauge options are:

V1/200P	Double acting/air assist	3	0-160 PSI	
V1/200P	Single acting	2	0-160 PSI	
V1/200P	Signal gauge-optional	1	· 0-30 PSI	Useful when checking remote lp
V1/200E	Double acting/air assist	3	0-160 PSI	
	_	1	0-30 PSI	•
V1/200E	Single acting	2	0-160 PSI	
	,	1	0-30 PSI	

^{*}Air assist-(optional)Means connecting the supply air(through the C-port) to the spring side of a single acting actuator will sometimes stabilize the package, and help prevent from drawing unwanted air, water, or other undesirable material into the spring side of the actuator.

