




# V200 POSITIONER

www.vacaccessories.com


## 1. WIRING DIAGRAMS

Screw terminals, overview



### Terminal assignment


Standard IP Transducer




Loop Input  
4 - 20 mA




### Position Feedback




2 SPDT Mechanical Switches  
Camden CSM30520D




2 SPDT Magnetic sensors  
Hamlin Reed 9145



2 Inductive Sensors NAMUR  
P+F NJ2-V3-N



Resistive Output  
0 - 10K ohm  
0 - 1K ohm



Current Output

